



Rare Earth Magnets

HAZARD WARNING

These magnets are the most powerful known. They are made by sintering (compressing and heating powdered materials) and are extremely brittle. When close enough, they will accelerate rapidly towards one another causing:

Trapped skin

Fracture of the magnets*

Especially in relation to the larger magnets, take extreme care to keep two or more magnets apart and only bring them together under tightly controlled conditions.

Do not bring the magnets into the proximity with sensitive electronic equipment – e.g., computer monitors, credit cards etc.

***Note:**

There is a risk, but a relatively low one, of chips flying off. Tests show that fragments adhere together at the point of collision.